

Performance of Retrofitted Concrete Buildings during the September 19, 2017 Earthquake in Mexico City

Juan MURCIA-DELISO

Assistant Professor

University of Texas at Austin

Austin, Texas, United States

murcia@utexas.edu

Dr. Juan Murcia-Delso is an Assistant Professor at the University of Texas at Austin. His technical interests include the behaviour, analysis, design, and retrofit methods for concrete structures.



Contact: murcia@utexas.edu

Oriol ARNAU

Researcher / Consultant

Instituto de Ingeniería - UNAM / Iktes

México City, México

oriol@iktes.com

Dr. Oriol Arnau is a researcher and consultant specialized in the study and simulation of the nonlinear response of concrete and masonry structures.



1 Abstract

The 1985 Mexico City earthquake resulted in extensive damage and collapse of concrete construction. In the months and years following this earthquake, there was an unparalleled effort to repair and retrofit concrete buildings. On September 19, 2017, a new strong earthquake struck Mexico City. This event represented the first severe test for concrete buildings retrofitted after 1985, providing an unprecedented opportunity to study the actual performance of the retrofit techniques applied in these buildings. This paper presents results of a field investigation and damage assessment of three retrofitted concrete buildings after the 2017 earthquake. The structures studied suffered different levels of damage during the 1985 earthquake, and they were subsequently repaired and retrofitted using a variety of techniques (e.g., jacketing of columns and beams, addition of steel bracing, RC infill walls). Except for the excessive tilting of one of the structures, the buildings presented minor damage after the 2017 event. The shaking intensities of 2017 can be considered similar to those of 1985 in the period range of interest for these buildings, while the structures presented in general better performance thanks to an increase of their capacity and/or a decrease of the seismic demands.

Keywords: earthquake, retrofit, repair, rehabilitation, concrete buildings, jacketing, steel bracing, Mexico City.

2 Introduction

The 1985 Mexico City earthquake resulted in extensive damage and collapse of modern concrete construction. In the months and years following this earthquake, there was an unparalleled effort to repair and retrofit concrete buildings. Jara *et al.* [1],[2] and Aguilar *et al.* [3] studied and documented repair and retrofit activities undertaken in a dozen of reinforced concrete buildings. Interventions ranged from local upgrades

of concrete elements (e.g., jacketing of columns and beams) to changes in the lateral force resisting systems (e.g., steel bracing, addition of shear walls). These retrofit methods were developed based on engineering judgement using strategies that in most cases had not been previously validated with experimental studies or refined numerical modeling.

On September 19, 2017, a new strong earthquake struck Mexico City. The earthquake caused 369 deaths, 228 of them in Mexico City, and damaged